

Commissioner: Michael D. Jarrett

John B. Pate, MD, Chairman

William E. Applegate, III, Vice Chairman John H. Burriss, Secretary

Promoting Health, Protecting the Environment

March 19, 1991

Other: Toney Graham, Jr., MD Richard E. Jabbour, DDS

Henry S. Jordan, MD Currie B. Spivey, Jr.



Jon Bornholm Remedial Project Manager U.S. EPA, Region IV 345 Courtland Street Atlanta, GA 30365

RE: Medley Farms Final RI Report

Dear Mr. Bornholm:

For the most part, the Department feels its comments were addressed adequately by Sirrine. We still have the concerns outlined below.

Page 8, 4th Bullet; Page 109, Section 5.2; Page 155, Section 6.0, 3rd Paragraph; Page 163, Section 7.0, Conclusion 4.

A statement needs to be included in the Executive Summary and Section 7.0 that while PCBs were not found above TSCA Action Levels, they will be evaluated in the Risk Assessment. The text as presently written leads the reader to believe that PCBs will not be evaluated.

Page 66, Section 3.7.1, Monitoring Well Location Rationale

The rationale for well pairs 108 and 109 needs to be presented. The explanation of why BW107 was not installed should be included in the text.

Page 77, Section 3.8.3

Hydraulic conductivity of saprolite wells ranged from 2.96 x 10^{-3} to 3.05 x 10^{-5} cm/sec, not 3.8 x 10^{-5} to 7.79 x 10^{-4} cm/sec. This mistake was changed in Section 4.2.1.

Page 137, Section 5.7.1, Second Paragraph

A statement should be added to the text stating that correspondence from the laboratory about inconsistent results is included in Appendix L.





Jon Bornholm March 19, 1991 Page 2

If you have any questions, please call me at (803)734-5487.

Sincerely,

Richard Haynes

Richard Haynes Site Engineering Section

Bureau of Solid and Hazardous Waste Management

RH/njw

cc: Angela Gorman

Charles Lewis